



Legislation Details (With Text)

**File #:** 24-671      **Version:** 1      **Name:**  
**Type:** Business Item      **Status:** Agenda Ready  
**File created:** 6/27/2024      **In control:** Traffic Committee  
**On agenda:** 7/9/2024      **Final action:**  
**Title:** SUBJECT: REQUEST #24-38 Requesting The Installation Of Speed Bumps And A Temporary Speed Trailer On Northwood Drive.

REPORT IN BRIEF

Citizen explains many drivers use Northwood Drive as a throughway to avoid the traffic on Olive Ave and Bear Creek Dr. These vehicles travel at high speeds, causing safety hazards to residents of this area, many of whom include both children and elderly veterans who enjoy spending time outside frequently. The potential risk of an accident has led some fearful residents to discontinue the walks outdoors. The installation of speeds bumps could urge drivers to slow down and would allow for a safer environment for all residents and drivers in the area. A temporary speed radar would be beneficial until speeds bumps are installed.

Sponsors:

Indexes:

Code sections:

**Attachments:** 1. REQUEST #24-38

Date	Ver.	Action By	Action	Result
------	------	-----------	--------	--------

*Report Prepared by: Alivia Alfaro, Administrative Assistant II, Engineering*

**SUBJECT:** REQUEST #24-38 Requesting The Installation Of Speed Bumps And A Temporary Speed Trailer On Northwood Drive.

REPORT IN BRIEF

Citizen explains many drivers use Northwood Drive as a throughway to avoid the traffic on Olive Ave and Bear Creek Dr. These vehicles travel at high speeds, causing safety hazards to residents of this area, many of whom include both children and elderly veterans who enjoy spending time outside frequently. The potential risk of an accident has led some fearful residents to discontinue the walks outdoors. The installation of speeds bumps could urge drivers to slow down and would allow for a safer environment for all residents and drivers in the area. A temporary speed radar would be beneficial until speeds bumps are installed.

ATTACHMENTS

- 1. Request #24-38